

Division of Oil, Gas, & Mining  
Mining Report

03/22/94

MINE ID: M0270008

MINE NAME: SEVIER DRY LAKE PROJECT

OPERATOR: CRYSTAL PEAK MINERALS CORP.  
CONTACT: MR. LARRY SOWER  
ADDRESS: P.O. BOX 100  
MILFORD UT 84751

PHONE: (801)387-5542

Surface Owner: BLM, UT  
Mineral Owner: BLM, UT

BLM #: U-37863-7912  
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	E2	NW				4	24.0S	12.0W

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): SUS

Acreage: 0

Minerals Mined  
SALINES/POTASH

DATE  
RECEIVED

TENTATIVE APPROVAL  
DATE

FINAL APPROVAL  
DATE

LAST INSPECTED

03/07/86

08/06/86

08/27/87

03/04/94

BOND TYPE: SURETY/BOARD CONT

BOND AMOUNT: \$\$\$\$117,000

ANNUAL REPORT YEAR: 93

	YTD	Total					
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/

COMMENTS:

1993 REPORT STATED THAT RECLAMATION WAS COMPLETE. OPERATOR REQUESTED SURETY RELEASE IN 10/93. INSPECTION MADE SPRING OF '94 TO DETERMINE COMPLETENESS. EARTH WORK AT THE CAMP AREA WAS COMMENDABLE. THE MAIN DIKE WAS BREACHED NEAR THE LAKE SHORE LINE & AT THE INFLOW CANAL PUMP AREA. OPERATOR HAS BEEN ASKED TO DO ONE FINAL CLEANUP OF DEBRIS. A PORTION OF THE BOND WILL HAVE TO BE LEFT IN PLACE FOR REVEGETATION STANDARDS. OPERATOR WISHES TO TRANSFER 5,000 BOND FROM STATE LANDS TO DOGM FOR THIS PURPOSE. ATTORNEY (GUSHEE) WILL CHECK INTO THIS.